



## Bi-pass clamp: ②



← Downward printing


← Side printing

## If leaking: ③



Adjust bi-pass clam downward slightly, wait for 5 minutes, until no leakage

## if no printing: ③



Adjust bi-pass clam upward slightly, wait 5 minutes until no leakage, then print

## Precaution:

